

UNIVERSITY OF PUNE
[4363]-163
T.E Electrical Examination - 2013
ELECTRICAL MACHINES-II
(2008 COURSE)

[Total No. of Questions :12]
[Time : 3 Hours]

[Total No. of Printed Pages :4]
[Max. Marks : 100]

Instructions :

- (1) Answer **three** question from each section.
- (2) Answers to the **two sections** should be written in **separate answer-books**.
- (3) Black figures to the right indicate full marks.
- (4) Neat diagrams must be drawn wherever necessary.
- (5) Use of logarithmic tables slide rule, Mollier charts, electronic pocket calculator is allowed.
- (6) Assume suitable data, if necessary.

SECTION I

- Q1 a) Define voltage regulation of alternator. Explain why Potier method gives more accurate results than synchronous impedance method. [6]
- b) Compare salient pole & non salient type of alternators. [4]
- c) A 1500 KVA, 6.6 KV 3 phase star connected alternator has effective armature resistance of $0.5 \Omega/\text{ph}$ & synchronous reactance of $5\Omega/\text{ph}$. Find the voltage regulation at (i) unity pf (ii) 0.8 lagging pf. [8]

OR

- Q2 a) What is armature reaction in case of three phase alternator? Explain its effect on the working of the alternator. [6]
- b) Derive the expression for emf induced in case of a 3 phase alternator. [4]
- c) A 1200 kVA, 3300 V, 50 Hz, 3-phase, star connected alternator has armature resistance of 0.25Ω per phase. A field current of 40 A produces a short circuit current of 200 A and an open circuit emf of 1100 V line to line. Find the voltage regulation on (i) full load 0.8 pf lag (ii) full load 0.8 pf leading [8]

Q3 a) Explain the advantages of synchronizations of 3-phase alternators. Explain one dark & two bright lamp method for used for synchronizing of 3-phase alternator. [8]

b) The 11,000v, 3 phase star connected synchronize motor takes current of 60 Amp. The effective resistance & synchronize reactance per phase are respectively 1Ω and 30Ω . Find (1) the power supplied to the motor at 0.8 pf (2) induced emf for a power factor of 0.8 lead (3) induced emf for a power factor of 0.8 lagging [8]

OR

Q4 a) Explain operation & synchronize motor at [8]

1) Constant load & variable excitation

2) Constant excitation & variable load

b) A 3 phase alternator has direct axis synchronous reactance of 0.85 pu & quadrature axis synchronize reactance of 0.55 pu. Determine the load angle, the no load p.u. voltage & per unit voltage regulation for the alternator when operating on full load at 0.8 p.f lagging. [8]

Q5 a) State different methods of speed control of 3-phase Induction motor. Explain v/f method of speed control of 3-phase Induction motor [8]

b) Write a short note on 3 phase induction generator [8]

OR

Q6 a) Compare 3 phase induction motor with three phase synchronizes induction motor. [8]

b) Write a note on testing of 3-phase induction motor as per IS 325 & IS 402g [8]

SECTION-II

Q7 a) Explain the operation of d.c. series motor on a.c. supply and problems with a.c. operation. [8]

b) Draw the circle diagram of a plain series motor and explain? [8]

OR

Q8 a) Explain transformer and rotational e.m.f's in plain series motor. [8]

b) What are the types of compensated series motor? Describe each with circuit diagram. [8]

Q9 a) Explain with sketch the operation of brushless d.c. motor and the applications of it? [8]

b) Describe the working, characteristics and applications of permanent magnet stepper motor. [8]

OR

Q10 a) What are the types of harmonics and explain the remedies to reduce the harmonics? [8]

b) Explain the constructional features of variable reluctance type stepper motor. [8]

Q11 a) Draw the equivalent circuit of a single phase induction motor and discuss the experimental procedure to obtain its parameters. [8]

b) Explain the working principle and applications of single phase shaded pole motors. [4]

c) A 125W, 4 pole, 110V, 50Hz, single phase induction motor delivers rated output at a slip of 6%. The copper loss at full load is 25 Watts, calculate the full load efficiency & rotor copper loss caused by the backward field. Rotational losses may be assumed to be 25 Watts. Neglect stator copper loss. [6]

OR

Q12 a) Explain the cross field theory as applied to a single phase induction motor. [4]

b) What are the methods to make single phase induction motors self starting? Explain in detail with operation, characteristics. Characteristics of capacitor start motors. [6]

c) The constants of a 0.25 H.P., 230 V 4-pole, 60 Hz, single phase induction motor are as follows: [8]

stator resistance $R_1 = 10\Omega$

stator reactance $X_1 = 12.8\Omega$

Rotor resistance referred to stator $R_2^1 = 11.65\Omega$

Rotor reactance referred to stator $X_2^1 = 12.8\Omega$

Magnetising reactance $X_m = 258\Omega$

The total load is such that the machine runs at 3% slip, when the applied voltage is at 210V. The iron losses are 35.5 watts at 210 V. Calculate i) Input current ii) power developed iii) shaft power if mechanical losses are 7 watts. And iv) efficiency.
